

Architectural Coatings

*Seal Grip Interior/Exterior Alkyd Universal Primer/Sealer***GENERAL DESCRIPTION**

Our best professional interior/exterior alkyd primer formulated to meet the performance requirements of residential and commercial markets. *Seal Grip* Interior/Exterior Alkyd Universal Primer/Sealer provides both excellent adhesion to a wide range of surfaces and stain blocking over a variety of common stains including water, nicotine, smoke, ink, markers, and wood tannin stains. It can be recoated in 4 hours, and unlike other fast dry oil primers, it is suitable for most exterior surfaces.

**RECOMMENDED SUBSTRATES**

|                      |                          |
|----------------------|--------------------------|
| Aluminum Siding      | Gypsum Wallboard-Drywall |
| Brick                | Plaster                  |
| Concrete/Masonry     | Stucco                   |
| Concrete Block (CMU) | Wood                     |

**CONFORMANCE STANDARDS**

MPI Approved in Categories #5, #45, #46, #69, and #136

**PRODUCT INFORMATION**

17-941NF                      White (Tintable)

May be tinted toward the finish coat color with up to four oz./gal. of colorants.

**PACKAGING**1-Gallon (3.78 L)  
5-Gallon (18.9 L)**PRODUCT DATA**

|                       |                                        |
|-----------------------|----------------------------------------|
| <b>PRODUCT TYPE:</b>  | Alkyd                                  |
| <b>SHEEN:</b>         | Low Sheen                              |
| <b>VOLUME SOLIDS:</b> | 57% +/- 2%                             |
| <b>WEIGHT SOLIDS:</b> | 74% +/- 2%                             |
| <b>WEIGHT/GALLON:</b> | 11.0 lbs. (5.0 kg) +/- 0.2 lbs. (91 g) |
| <b>VOC:</b>           | < 350 g/L (2.9 lbs./gal.)              |

**COVERAGE:** Approximately 400 sq. ft. (37 sq. meters) per U.S. Gallon (3.78L) on smooth, nonporous surfaces.

|                     |          |
|---------------------|----------|
| Wet Film Thickness: | 4.0 mils |
| Wet Microns:        | 102      |
| Dry Film Thickness: | 2.3 mils |
| Dry Microns:        | 58       |

Coverage figures do not include loss due to surface irregularities and porosity or material loss due to application method or mixing. Some colors, drastic color changes, or porous substrates may require more than one coat to achieve a uniform finish.

|                                                                    |               |
|--------------------------------------------------------------------|---------------|
| <b>DRYING TIME:</b> Dry time @ 77°F (25°C); 50% relative humidity. |               |
| To Touch:                                                          | 30-60 minutes |
| To Recoat:                                                         | 4-6 hours     |

Drying times listed may vary depending on temperature, humidity, color, film build, and air movement.

**CLEANUP:** Clean tools with mineral spirits or high-quality paint thinner. **DANGER - RAGS, STEEL WOOL, OR WASTE SOAKED WITH SEAL GRIP PRIMER MAY SPONTANEOUSLY CATCH FIRE IF IMPROPERLY DISCARDED. IMMEDIATELY AFTER EACH USE, PLACE RAGS, STEEL WOOL, OR WASTE IN A SEALED, WATER-FILLED, METAL CONTAINER.**

**DISPOSAL:** Contact your local environmental regulatory agency for guidance on disposal of unused product. Do not pour down a drain or storm sewer.

|                     |              |
|---------------------|--------------|
| <b>FLASH POINT:</b> | 108°F (42°C) |
|---------------------|--------------|

**FEATURES / BENEFITS**

|                                                                                                                                               |                                                                                                                                                                                                                                   |
|-----------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>Features</b><br>Interior/Exterior Formula<br>Excellent Adhesion<br>Low Odor Alkyd<br>Stain Blocking<br><br>Great for Fire and Water Damage | <b>Benefits</b><br>Whole house primer<br>Adheres to a wide range of substrates<br>Less odor than traditional alkyds<br>Great at blocking out most stains (water, smoke, ink, markers, and tannins)<br>Perfect for restoration use |
|-----------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|

## GENERAL SURFACE PREPARATION

Surface must be clean and dry. Remove all loose, peeling paint, dirt, grease, and any other surface contaminants. Blistering and peeling issues are commonly caused by moisture behind the paint film. Problems leading to excessive moisture in the substrate must be repaired prior to painting. Putty all nail holes and caulk all cracks and open seams. Sand all glossy, rough, and patched surfaces. Plaster, concrete, and masonry surfaces must be completely dry, free of efflorescence, and allowed to cure for 30 days prior to painting.

**WARNING!** If you scrape, sand, or remove old paint, you may release lead dust or fumes. LEAD IS TOXIC. EXPOSURE TO LEAD DUST OR FUMES CAN CAUSE SERIOUS ILLNESS, SUCH AS BRAIN DAMAGE, ESPECIALLY IN CHILDREN. PREGNANT WOMEN SHOULD ALSO AVOID EXPOSURE. Wear a properly fitted, NIOSH-approved respirator and prevent skin contact to control lead exposure. Clean up carefully with a HEPA vacuum and a wet mop. Before you start, find out how to protect yourself and your family by contacting the USEPA National Lead Information Hotline at 1-800-424-LEAD or log on to [www.epa.gov/lead](http://www.epa.gov/lead). Follow these instructions to control exposure to other hazardous substances that may be released during surface preparation.

**ALUMINUM SIDING:** Aluminum siding may present potential adhesion problems. Prime prior to topcoating. Primer should be spot applied, allowed to cure overnight, then evaluated for adhesion. Check adhesion by applying a piece of masking tape. If adhesion is good, the application may proceed. If the coating peels off when the masking tape is removed, the surface must be scuff sanded prior to proceeding to ensure mechanical adhesion.

**BRICK, CONCRETE, and MASONRY:** New concrete and masonry should cure for at least 30 days and preferably 90 days prior to priming and painting. The pH of the substrate must be less than 10 before priming. Painting glazed brick is not recommended due to potential adhesion problems.

**CONCRETE BLOCK (CMU):** Mortar should cure for at least 30 days and preferably 90 days prior to priming. Fill block with an appropriate block filler. Surfaces previously coated with water thinned cement-based paint must be prepared with extra care. If the material appears to be adhering tightly, a masonry sealer may be applied to seal the surface. Check adhesion by applying a piece of masking tape. If the sealer peels off and has loose particles, remove all chalking or crumbling material, re-seal and re-check adhesion.

**GYPSUM WALLBOARD-DRYWALL:** Nails or screws should be countersunk, and they along with any indentations should be mudded flush with the surface, sanded smooth and cleaned to remove any dust, then prime prior to painting the substrate.

**PLASTER:** Plaster, hardcoat, skim coat, or other alkaline surfaces should be allowed to cure for at least 30 days and preferably 90 days prior to priming.

**STUCCO:** New stucco should cure for at least 30 days and preferably 90 days prior to priming and painting. The pH of the substrate must be less than 10 before priming. Surface chalk from the curing or aging process should be removed then sealed with an appropriate sealer to rebind and restore the surface to a sound condition.

**WOOD:** Unpainted wood or wood in poor condition should be sanded smooth and wiped clean. Any knots or resinous areas must be primed before painting. Countersink all nails, putty flush with surface, then prime.

## RECOMMENDED PRIMERS

|                      |        |
|----------------------|--------|
| Concrete Block (CMU) | 6-15XI |
|----------------------|--------|

## LIMITATIONS OF USE

Apply only when air, surface, and product temperatures are between 50°F (10°C) and 90°F (32°C) and at least 5°F (3°C) above the dew point. Air and surface temperatures must remain between 50°F (10°C) and 90°F (32°C) for the next 48 hours. Avoid painting in direct sunlight or on hot surfaces. Do not apply late in the day when dew and condensation are likely to form or if rain or snow is expected.

Do not use on solvent sensitive stains such as asphalt and tar. This product must be topcoated. The pH of the substrate must be less than 10 before priming. Extended period before topcoating may affect performance. Severe stains may require two coats of primer. Tinted primer may require additional drying time.

While this product provides a mildew resistant coating, growth may still occur if the substrate is not properly prepared prior to painting and/or if the substrate is consistently exposed to conditions conducive to mold, mildew, and algae.

**APPLICATION INFORMATION**

Stir thoroughly before using and occasionally when in use. When using more than one container of the same color, intermix to ensure color uniformity. USE WITH ADEQUATE VENTILATION. KEEP OUT OF REACH OF CHILDREN. Read all label and Safety Data Sheet (SDS) information prior to use. SDS are available through our web site or by calling 1-800-441-9695.

**Application Equipment:** Apply with a high-quality brush, roller (nap size - 3/8" for smooth surfaces and up to 3/4" for rough or textured surfaces), paint pad, or by spray equipment. Spread evenly and quickly, keeping the leading edge wet. Avoid reworking previously painted areas. Severe stains may require two coats of primer.

**Airless Spray:** For airless spray application, use tip size .015" to .019" and pressure range of 1800 to 2400 psi. Spray equipment must be handled with due care and in accordance with manufacturer's recommendation. High-pressure injection of coatings into the skin by airless equipment may cause serious injury.

Explosion-proof equipment must be used when coating with these materials in confined areas. Keep containers closed and away from heat, sparks, and flames when not in use.

**Brush:** Natural Bristle Brush

**Roller:** 3/8" - 3/4" nap roller cover

**Thinning:** Do not thin.

**Permissible temperatures during application:**

Material: 50 to 90°F (10 to 32°C)

Ambient: 50 to 90°F (10 to 32°C)

Substrate: 50 to 90°F (10 to 32°C)

**PRECAUTIONS**

For warning information, please refer to the product label and SDS available at the online listing for this product at [www.pittsburghpaintsco.com](http://www.pittsburghpaintsco.com). Keep container tightly closed and sealed until ready for use. SDS, spill, and emergency information are available by calling 1-833-477-1553.

© 2026 The Pittsburgh Paints Co. All Rights Reserved. *Seal Grip* is a registered trademark, and the *P Logo & Pittsburgh Paints* are trademarks of The Pittsburgh Paints Co.

The Pittsburgh Paints Co. believes the technical data presented is currently accurate; however, no guarantee of accuracy, comprehensiveness, or performance is given or implied. Improvements in coatings technology may cause future technical data to vary from what is in this bulletin. For complete, up-to-date technical information, call 1-800-441-9695.



The Pittsburgh Paints Company  
500 Cranberry Woods Drive  
Cranberry Township, PA 16066  
[www.pittsburghpaints.com](http://www.pittsburghpaints.com)

Technical Services  
1-800-441-9695

17-941NF - 10/2026